

INFINITY

Dry Brite Floor Finish/High Gloss/
Hard Surface Protection

SPECIAL FEATURES

- Dry Brite Finish
- High Gloss and Durability/Pliability
- Low maintenance
- Does not discolor or yellow
- Easy to use, clean and maintain
- Savings on time/chemicals/labor
- Fast drying/leveling

DIRECTIONS

For best results, strip floors with PS Infinity Stripper, neutralize and clear water rinse. Check pH of floor to ensure it is neutral. For porous floors, new floors, or high traffic areas apply 4-5 coats of PS Infinity. For non-porous floors, simply apply 4 coats of PS Infinity Floor finish. For re-coating, clean floor thoroughly with PS Floor Cleaner, rinse and apply 1 to 3 coats of PS Infinity floor finish. Burnishing is not required. Restore with regular cleaning use of PS Floor Cleaner.

Properties

Appearance: Milky white
Finish Type: Acrylic
Polymer (Super Durable)
VOC's: 4 gm/L
Solid Content: 27%
pH: 8.5
Weight/Gallon: 10 lb
Coverage:
1500-2500 sq. ft./gallon
Soil Resistance: Excellent
Drying Time: 15-45 minutes
(depending on humidity)
Color of Dry Film: Water Clear
Application Temperature:
50 degrees F (Minimum)
Storage Temperature:
40 degrees F - 85 degrees F
Storage Stability:
1 year under normal conditions
Freeze Thaw Stability:
Passes one cycle

INFINITY exceeds Slip
Resistance standards when
tested according to ASTM
D3052-87: 0.5
(Slip Resistant)

STRIP, NEUTRALIZE, RINSE, 4-5 INFINITY COATS

Manufactured by:
Ultra Chem Labs Corp.
www.ultrachemlabs.com
Tel-909-605-1640
Fax-909-605-1068
4581 Brickell Privado
Ontario, CA 91761